


SERVICE BULLETIN

KAIR10001 – TANARG Fuel Tank

LANAS 16 April 2010

Re : Potential cracks in TANARG fuel tanks.

TRIKES CONCERNED : The TANARGs whose fuel tank was manufactured in since January 2008. (stamp visible as shown in the figures hereunder 08-04 or April 2008):



DESCRIPTION OF SYMPTOMS :

Potential appearance of cracks leading to fuel leaks.

CAUSE :

Not yet determined. Undergoing analysis by the manufacturer.

REQUIRED ACTION :

Regular and careful checks must be made and before every flight, in case of the appearance of cracks you should stop flying and contact our aftersales service for a replacement part.

It may prove useful to disassemble the keel of the trike (lower fairing) in order to gain visual access to the areas at risk.

