

SERVICE BULLETIN

KAIR 24001 – Safety Belts

September 6, 2024

Subject :

Checking the mounting direction of the belt buckle locking cam R071011 serial number R071011-2003

Models concerned : All trike models.

DESCRIPTION of the PROBLEM :

Seat belts are one of the most important safety components. We found that the seat belt buckle locking cam part number: R071011 was mounted upside down on 1 part of the R071011-2003 series. This assembly defect could affect the proper functioning of the lap belt.

REQUIRED ACTION :

1st : Please check the serial number of the seat belt buckles fitted to your trike (Sticker affixed to the inside of the buckle).

2nd : Checking the assembly of the locking cam in the loop R071011-2003.

Please check all the buckles fitted to your seat belts based on the photos below.

**Belt Buckle R071011-2003 :
Incorrect Assembly :**



**Belt Buckle R071011-2003 :
Correct Assembly :**



3rd : Complete the document below and return it to the address: chausse.s@aircreation.fr

	Serial Number	Correct Assembly
Front Buckle		Yes / No
Rear Buckle		Yes / No

If you have a buckle that is not properly mounted, please discontinue use of the trike and send us a photo of the buckle so that we can exchange it.